

Rotary
Club San Salvador



2021 REPORT

VISIT TO SCHOOLS OF THE WASH PROYECT



VISITS

Club Rotario de San Salvador



A visit was made to 5 schools in the municipalities of Chiltiupán and Jicalapa in order to pick the schools to intervene with the WASH in schools project. Both municipalities are located in the coastal area of La Libertad.

The schools visited were:

- Centro Escolar Cantón La Perla.
- Centro Escolar Cantón La Pedrera.
- Centro Escolar Hermosa Provincia.
- Centro Escolar El Zonte.
- Centro Escolar Santo Domingo

In all these schools we found problems in the toilets, sinks, drinking water network, kitchens and lunch areas.

SCHOOL: LA PERLA

EVALUATION

Location:

La Perla School is located in the municipality of Jicalapa, department of La Libertad.

General Conditions:

- has good accessibility.
- It has drinking water service
- Toilets in fair condition but improvements are needed.
- Kitchen is in poor condition.
- Broken rain gutters
- It has more than 100 students.
- It has a tank for for drinking water and has a septic tank.
- It does not have a dining area.
- Teachers and students have not received training in hygiene and sanitation.





PHOTOS OF LA PERLA SCHOOL



SINK INSPECTION



BATHROOMS AND WATER TANK



DAMAGED GUTTERS



WORK TO BE DONE AND COST ESTIMATE

	ESTIMATED COST
BATHROOMS	\$3,000
Laboratory tests to determine water quality	
Cleaning the septic pit	
Toilets	
Walls and Floors	
Oil Paint	
Review of Electrical Instalations	
Construction of Menstrual Toilet	
Mirrors, Soap Dispensers, Garbage Bins and other Accessories	
Rain Water Channel Repair	
HAND WASHING AREA	\$2,500
Ceilings over hand washing area	
Change of faucet	
Sink Plated with tile	
Changing control valves and supply tubes	
KITCHEN, FOOD WASHING AREA AND FOOD PREPARING AREA	\$1,500
Purchase of wood saving kitchens	
Floors and wall plating with ceramic	
Construction of the food prepping table plated with tiles	
LUNCH AREA	\$2,500
Construction of concrete tables and benches with a tile plated surface.	
Construction of ceiling over dining area	
CONSTRUCTION MANAGEMENT	\$2,000
Project Supervisor	
	\$11,500

Construction Cost: **\$11,500**

Training Cost: **\$1,500**

TOTAL COST ESTIMATE LA PERLA

\$ 13,000

SCHOOL: LA PEDRERA


EVALUATION

Location:

La Pedrera School Center is located in the municipality of Jicalapa, department of La Libertad.

General Conditions:

- It has good accessibility.
- It has drinking water service
- Toilets in fair condition but improvements are needed.
- Kitchen is in fair condition.
- It has more than 100 students.
- It has a septic tank and tank for drinking water.
- It does not have a lunch area.
- Teachers and students have not received training in hygiene and sanitation.



PHOTOS OF LA PEDRERA SCHOOL



WORK TO BE DONE AND COST ESTIMATE

	Estimated Cost
BATHROOM	\$3,000
Laboratory tests to determine water quality	
Change of Toilets	
Ceramic Plated Walls and Floors	
Oil Paint	
Review of Electrical Installations	
Construction of Menstrual Bathroom	
Mirrors, Soap Dispensers, Garbage Bins and other Accessories	
HAND WASHING AREA	\$1,800
Ceilings over hand washing area	
Change of faucet	
Sink Plated with tile	
Changing control valves and supply tubes	
KITCHEN, FOOD WASHING AREA AND FOOD PREPARING AREA	\$1,200
Purchase of wood saving kitchens	
Floors and wall plating with ceramic	
Construction of the food prepping table plated with tiles	
LUNCH AREA	\$700
Plate with tiles the existing tables	
CONSTRUCTION MANAGEMENT	\$1,800
Project Supervisor	
	\$8,500

Construction Cost: **\$8,500**

Training Cost: **\$1,500**

TOTAL COST ESTIMATE LA PEDRERA

\$ 10,000

SCHOOL: HERMOSA PROVINCIA

EVALUATION

Location:

The Hermosa Provincia School is located in the municipality of Jicalapa, department of La Libertad.

General Conditions:

- The school is in very bad condition.
- It has good accessibility.
- It has drinking water service
- Toilets in very bad condition.
- Kitchen is in bad condition.
- It has more than 100 students.
- Kitchen is in bad condition and without the conditions for food handling.
- It has a septic Tank.
- Damaged water tank.
- Teachers and students have not received training in hygiene and sanitation.



PHOTOS OF HERMOSA PROVINCIA SCHOOL



TOILETS



BATHROOMS



ELEVATED TANK



CLASSROOMS

WORK TO BE DONE AND COST ESTIMATE

	Estimated Cost
BATHROOMS	\$5,500
Laboratory tests to determine water quality	
Complete Bathroom Rehabilitation	
Change of Toilets	
Ceramic Plated Walls and Floors	
Oil Paint	
Review of Electrical Installations	
Construction of Menstrual Bathroom	
Mirrors, Soap Dispensers, Garbage Bins and other Accessories	
HAND WASHING AREA	\$3,000
Ceilings over hand washing area	
Change of faucet	
Sink Plated with tile	
Changing control valves and supply tubes	
KITCHEN, FOOD WASHING AREA AND FOOD PREPARING AREA	\$2,500
Purchase of wood saving kitchens	
Construction of Kitchen	
Construction of the food prepping table plated with tiles	
LUNCH AREA	\$1,500
Construction of roof, tables and benches for lunch area	
CONSTRUCTION MANAGEMENT	\$2,000
Project Supervisor	
	\$14,500

Construction Cost: **\$14,500**

Training Cost: **\$1,500**

TOTAL COST ESTIMATE HERMOSA PROVINCIA

\$ 16,000

SCHOOL: EL ZONTE


EVALUATION

Location:

El Zonete School Center is located in Cantón El Zonte, department of La Libertad.

General Conditions:

- The school is in good condition and has good accessibility.
- It has drinking water service
- Toilets in good condition few improvements are needed.
- Kitchen in fair conditions but improvements are needed.
- It has more than 100 students.
- It has a septic Tank and water Tank.
- Lunch Area needs improvement.
- Teachers and students have not received training in hygiene and sanitation.



PHOTOS OF EL ZONTE SCHOOL



TOILETS



BATHROOMS



KITCHEN



ELEVATED WATER TANK

WORK TO BE DONE AND COST ESTIMATE

	Estimated Cost
BATHROOM	\$1,500
Laboratory tests to determine water quality	
Change of Toilet accessories	
Ceramic Plated Walls and Floors	
Oil Paint	
Construction of Menstrual Bathroom	
Mirrors, Soap Dispensers, Garbage Bins and other Accessories	
HAND WASHING AREA	\$1,000
Ceilings over hand washing area	
Change of faucet	
Sink Plated with tile	
Changing control valves and supply tubes	
KITCHEN, FOOD WASHING AREA AND FOOD PREPARING AREA	\$800
Purchase of wood saving kitchens	
Kitchen repairs	
CONSTRUCTION MANAGEMENT	\$1,200
Project Supervisor	
	\$4,500

Construction Cost: **\$4,500**

Training Cost: **\$1.500**

TOTAL COST ESTIMATE EL ZONTE

\$ 6,000

SCHOOL: SANTO DOMINGO



EVALUATION

Location:

The Santo Domingo School is located in Caserío Santo Domingo, Municipality of Chiltiupán, La Libertad.

General Conditions:

- The school is in good condition.
- It has good accessibility.
- It has drinking water service
- Bathrooms are in fair conditions.
- Kitchen is in fair condition.
- It has no lunch area.
- It has a septic Tank and water tank.
- Teachers and students have not received training in hygiene and sanitation.



PHOTOS OF SANTO DOMINGO SCHOOL



SINK



KINDERGARTEN SINK



KITCHEN



TOILET

WORK TO BE DONE AND COST ESTIMATE

	Estimated Cost
BATHROOM	\$1,500
Laboratory tests to determine water quality	
Cleaning the septic Pit	
Complete Bathroom Rehabilitation	
Change of Toilet accessories	
Ceramic Plated Walls and Floors	
Oil Paint	
Review of Electrical Installations	
Construction of Menstrual Bathroom	
Mirrors, Soap Dispensers, Garbage Bins and other Accessories	
HAND WASHING AREA	\$1,000
Ceilings over hand washing area	
Change of faucet	
Sink Plated with tile	
Changing control valves and supply tubes	
KITCHEN, FOOD WASHING AREA AND FOOD PREPARING AREA	\$500
Purchase of wood saving kitchens	
Construction of Kitchen	
Construction of the food prepping table plated with tiles	
CONSTRUCTION MANAGEMENT	\$1,200
Project Supervisor	
	\$4,200

Construction Cost: **\$4,200**

Training Cost: **\$800**

TOTAL COST ESTIMATE SANTO DOMINGO

\$ 5,000

TOTAL COST ESTIMATE FOR THE PROJECT

La Perla School:	\$13,000
La Pedrera School:	\$10,000
Hermosa Provincia School:	\$16,000
El Zonte School:	\$6,000
Santa Domingo School:	\$5,000

TOTAL: \$50,000

