

THE PICTORIAL  
VERSION OF THE  
STATUS OF THE  
HPRC MATERNITY  
WING





**This is the Bed where mothers give birth from. They are three of them and quite won out.**





**The Exterior view of the Maternity ward of the HPRC**







**Above;** Where the Mothers Give birth from; and **Below;** the inside of the maternity Wing





**The dilapidated ceiling in the maternity ward; where mothers and their babies stay after giving birth**







**Above;** dilapidated wall at entrance of the ward; **Below;** Inside one of the rooms; broken beds





**Entrance to the Bathrooms and Toilets**





**Above; at the entrance of the bathrooms; Below, a glimpse at the bathrooms used by fresh mothers**





Above: The toilets used by the mothers. Below: The Washing Sink and the second set of shower rooms







A peep at the inside of the toilets that fresh mothers use







Above: The toilets and Below; The bathrooms and the washing area





Above; Out side the Kitchen Area where mothers cook their meals from. Below: the inside of the kitchen

